

Inspection Report for Flood Damage work

ite:-

me of PIUS :-

me of Block :-

me of Road :-

RWD (W) Division udakithungani
Alamnagar
Shankarpur Madheli Bisunpur chandalar road.

or Road

Damage Location/Chainage :- 0.00 K.M to 6.00 K.M, 6.00 K.M to 12.00 K.M

Damage Length :- 350.00 M

Nature of damage :- Due to flood, heavy rain.

Details of Restoration Works :- restoration work with brick bats.

Material being used in Restoration works :- Brick Bats.

Equipments/Tools being used in Restoration works :- Tractor, Manual.

Procedure taken up in Restoration works :- Tractor, Manual.

Restored Length :- 350.00 M.

For Bridge

Damage Location/Chainage :-

Damage Length :-

Nature of damage :-

Details of Restoration Works :-


i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-


iii Procedure taken up in Restoration works :-

iv Restored Length :-


JE


AE


EE


Signature
(Name of inspector)

(These four lines should be repeated at the commencement of the measurement relating to each work)

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
7th to 6th M.					
3 x 9.00 x 2.50 x 0.30 =					20.250 M ³
5 x 8.00 x 3.00 x 0.45 =					54.000 M ³
8 x 8.00 x 2.50 x 0.40 =					64.000 M ³
6 x 6.00 x 3.00 x 0.50 =					37.800 M ³
5 x 4.00 x 2.75 x 0.40 =					22.000 M ³
5 x 5.00 x 3.00 x 0.30 =					22.250 M ³
6th K-M to 12.0 K-M					

[illegible]

Continuation

① Port & lying of
side not returned
form . . . cell
V.T. M.B. P-02
510.204³@1874.97- MS. 956609.69

As 956609.69

Ad 127, GST- Q3 114793.16

add'l. class - RS 956.09

1080	968	72
------	-----	----

Say Rs 1080969.00

05/02/21
JL

A

cap

1710221

AP
5-2-25
AE