

Inspection Report for Flood Damage work

Date:-
Name of PIUS :- RWD (N) Division Udaipur
Name of Block :- Alam nagar
Name of Road :- Pakant To RWD Road Elhara

For Road

Damage Location/Chainage :- 0.0 to 0.900 K.M
Damage Length :- 250.0 M
Nature of damage :- Plank.
Details of Restoration Works :- e. cement bag with L. sand.
Material being used in Restoration works:- empty cement bag, L. sand.
Equipments/Tools being used in Restoration works :- Tractor, Manual.
Procedure taken up in Restoration works :- Manual.
Restored Length :- 250.0 M

For Bridge

1 Damage Location/Chainage :-
2 Damage Length :-
3 Nature of damage :-
4 Details of Restoration Works :-
i Material being used in Restoration works:-
ii Equipments/Tools being used in Restoration works :-
iii Procedure taken up in Restoration works :-
iv Restored Length :-

JE
25/12/20

AE
25/12/20

EE
25/12/20

Signature
(Name of inspector)
25/12/20

(These four lines should be repeated at the commencement of the measurement relating to each work)

① labor for filling
e-concrete bags with
L-sand - old do
Camp job - CLP

$2 \times 50.0 \times 2.0 \times 5.0 = 4000.00$ bags
 $2 \times 45.0 \times 6.0 \times 5.0 = 2700.00$ bags
 $2 \times 75 \times 5.0 \times 5.0 = 3750.00$ bags
 $2 \times 40.0 \times 8 \times 5.0 = 3200.00$ bags

05/02/21
A.E.

Continuation