

Inspection Report for Flood Damage Work

Date: 26.12.2020

1. Name of PIU:- EE/RWD/Barh

2. Name of Block/Road:- Pandamuk/Marigha Bigra to Baddepur

✓ 3. For Road:-

4. Damage Location/Chainage:-

5. Damage Length:- 0.045 km

6. Nature of Damage:- Discontinuity in communication due to incomplete slab cement

I. Material being used in Restoration Works:- Brick bats, ghana khon, NP₃ HP, local sand, cement bag

II. Equipments/Tools being used in Restoration Works:- Tractor, Front loader

III. Procedure taken up in Restoration Works:- SFF 0.60m ϕ NP₃ HP, laying, spreading ghana khon, brick pitching, laying & placing sand filled cement bags

IV. Restored Length:- 0.045 km

B. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

I. Material being used in Restoration Works:-

II. Equipments/Tools being used in Restoration Works:-

III. Procedure taken up in Restoration Works:-

IV. Restored Length

N/A

26.12.2020
Name of Inspector
Executive Engineer

R.W.D, Works Division

Patra