

Inspection Report for Flood Damage Work


Date: 26.12.2020

1. Name of PIU:- EE/RWD/Barh
2. Name of Block/Road:- Barh ^{Nadwa to} ^{via} Fatehpur ^{Nakshchak Road}
3. For Road:-
4. Damage Location/Chainage:-
5. Damage Length:- 0.117 Km
6. Nature of Damage:- A Large no. of depressions/pit holes due to heavy rainfall
- I. Material being used in Restoration Works:- GSB grt
- II. Equipments/Tools being used in Restoration Works:- Tractor, grader, roller, motor grader, roller
- III. Procedure taken up in Restoration Works:- Laying, spreading & Compacting GSB
- IV. Restored Length:- 0.117 Km

B. For Bridge

1. Damage Location/Chainage:-
2. Damage Length:-
3. Nature of Damage:-
4. Details of Restoration Works:-
- I. Material being used in Restoration Works:-
- II. Equipments/Tools being used in Restoration Works:-
- III. Procedure taken up in Restoration Works:-
- IV. Restored Length

14/A


26.12.2020
Name of Inspector
Executive Engineer Patna
R.W.D, Works Division