

Inspection Report for Flood Damage Work


Date: 26.12.2020

1. Name of PIU:- E E/RWD/ Barh
2. Name of Block/Road:- Pandam/ Ghatuapara PMSY Rd. to Dandpur
- ✓ 3. For Road:-
4. Damage Location/Chainage:-
5. Damage Length:- 0.740 km
6. Nature of Damage:- A large no. of depressions/pot holes due to heavy rainfall
- I. Material being used in Restoration Works:- GSB gr. I
- II. Equipments/Tools being used in Restoration Works:- Tractor, motor tinner, grader, Roller
- III. Procedure taken up in Restoration Works:- Laying, spreading & compacting GSB I
- IV. Restored Length:- 0.740 km

B. For Bridge

1. Damage Location/Chainage:-
2. Damage Length:-
3. Nature of Damage:-
4. Details of Restoration Works:-
- I. Material being used in Restoration Works:-
- II. Equipments/Tools being used in Restoration Works:-
- III. Procedure taken up in Restoration Works:-
- IV. Restored Length

N/A


Name of Inspector
Executive Engineer Patna
R.W.D, Works Division