

Inspection Report for Flood Damage Work

Date: 26.12.2020

1. Name of PIU: EE/RWD/Barh
2. Name of Block/Road: Pandarak/Pandarak Kundi Road to Sadikpur
- ✓ 3. For Road:-
 4. Damage Location/Chainage:-
 5. Damage Length:- 1.08 km
 6. Nature of Damage:- series of depressions/Pit holes in stretched due to heavy rainfall.
 1. Material being used in Restoration Works:- GSB gr. I
 - II. Equipments/Tools being used in Restoration Works:- Tractor, grader, roller, water tank, roller
 - III. Procedure taken up in Restoration Works:- Laying, spreading & compacting GSB I.
 - IV. Restored Length:- 1.08 km

B. For Bridge

1. Damage Location/Chainage:-
2. Damage Length:-
3. Nature of Damage:-
4. Details of Restoration Works:-
- I. Material being used in Restoration Works:-
- II. Equipments/Tools being used in Restoration Works:-
- III. Procedure taken up in Restoration Works:-
- IV. Restored Length

N/A


26.12.2020
Name of Inspector
Executive Engineer Patna
R.W.D, Works Division