## **Inspection Report for Flood Damage Work**

Date:-1 Name of PIUs: - Coyan vibral cook 2 Name of Block/Road: - ming bur / Bangherra pup Rd to Dharamphur (00-01) (A) For Road: 1. Damage Location/Chainage :- 0.301cm, 0.9501cm, 0.701cm 2. Damage Length :- 0.16031cm 3. Nature of Damage 4. Details of Restoration Works :-Material being used in Restoration works:- Bottle bat's (i) Equipment's/Tools being used in Restoration works:- Traceto (ii) Procedure taken up in Restoration works: (iii) Restored Length :- 0.1603 Km (iv) (B) For Bridge: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: (i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

CE

RWD muraffarpur Ger87-1

## **GENERAL ABSTRACT**

Name of Road

Banghara PWD Rd to Dharampur(00-01)

District

Muzaffarpur

Block

Minapur

Muzaffarpur East-2

Division

Length of Road (in Km)

2.210 Km

Jhama metal	
Sand Filling	
Sand bag	
H.P.	얼마 아내 왕이 없다면 동시하다 아이들의 사람이 되었다.
GRAND SUB TOTAL	

JΕ

RWD

Technically approved for RS 2.459 lac (Rubees Thro Lac forty bive thousand nine hundred only)

RWD HOME CITCLE MU2affarpur