

NH57 TO ARRAHA (GTSNY)

Schedule XLV-Form No. 134

MB NO - 1443

Supail

DIVISION

KISHANPUR

SUB-DIVISION

MEASUREMENT BOOK

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
10) Supply of Bamboo at site					
				Total (in m)	= 67.30
				Total (in nos)	= 9.61
				Qty =	10.00
8/10/2020 JE				(PUB) 27.10.2020 A.E.	

ABSTRACT OF Cost

1) Sand filling in foundation
Trenches as per Drawing &
Technical Specification

Qty = 627.06 m³ vide

TRB Pg no - (1)

@ 554.03 Rs/m³ Rs 347411.29

2) Providing & laying Brick
Bats.

Qty = 57.96 m³ vide TRB

Pg no - (2)

@ 1864.35 Rs/m³ Rs 108099.86

Continuation

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3) Labour for cutting 69mm to 75mm dia bamboo piles to — do —					
Qty = 22.00m vide TMB					
lg no (3)					
@ 27.90 Rs/m ³					Rs 613.80
4) Labours for fitting & straining 75mm dia bamboo running in position at every do —					
Qty = 22.30m vide TMB					
lg no (5)					
@ = 5.00 Rs/m					Rs 111.50
5) Supply of Bamboo tree at site					
Qty = 10.00 ^{nos} vide TMB lg no (6)					
@ 158.44 Rs/nos					Rs 1584.38
10) Providing & laying reinforced cement concrete pipe 11/3					
Qty = 15.00m vide					
TMB lg no (10)					
@ 3460.50 Rs/m					Rs 51907.50
					509,678.32

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					B.F = 509678.32
Add G.S.T @ 12%					61161.40
Add @ 1% labourers					5096.78
(A) Total					575,936.51

* Calculation of S.F

1) Sandfilling in foundation Trenches as per drawing & Technical Specification

Qty = 752.47 m³

(a) 141.85 Rs/m³ Rs 106738.49

2) Brick Ball.

Qty = 57.96 m³

@ 1063.00 Rs/m³ Rs 61606.83

168345.82

Signiorage fee @ 10%

of Basic Amount (B) Rs = 16835.00

Add (A) + (B) Rs 592771.50

Say Rs = 592771.00

28/10/2020
A.E

Continuation

Inspection Report for Flood Damage Work

Date :

1. Name of PUs :- EE RSD, Works Division Supd
2. Name of Block :- Kiskampur
3. Name of Road :- NH57 TO APRANA

A. For Road

1. Damage Location/Chainage : Ch :- 141 m, 153 m, 445 m, 466 m
469 m & 1300 m
2. Damage Length : 90.9 m
3. Nature of Damage : Due to flood

4. Details of Restoration Works :

- i. Material being used in Restoration work :- Hume pipe, Brick Bats
- ii. Equipments/Tools being used in Restoration work :- JCB, Tractor & Roller
- iii. Procedure taken up in Restoration work :- Filling
- iv. Restored Length :- 90.9 m

B. For Bridge

1. Damage Location/Chainage :

2. Nature of Damage :

3. Details of Restoration Works :

- i. Material being used in Restoration work :
- ii. Equipments/Tools being used in Restoration work :
- iii. Procedure taken up in Restoration work :
- iv. Restored Length :

N.A

25/11/2020

JE

25/11/2020

AE

25/11/2020
EE

Signature

(Name of Inspector)

EE RSD Polurungar