Block: - Bahadurgen J INSPECTION REPORT FOR ROUTINE MAINTENANCE

Date o	f Inspection: 26-11-2021 District: Kishangan J on: Kishangan I Length (km): 2358 BT-1.	-		
Divisio		750CC-0.608		
	of the Road: Loss to Belbari			
	Scheme/Programme: Pm 6.5 y. Sl. No. Parameters to be checked			
1.				
	Pavement Condition of Surfacing 5			
a)	Condition of Surfacing	5		
b)	Riding Quality			
c)	Road Camber	S		
d)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	5		
· e)	Contraction Joints provided or not (CC Pavement)	S		
f)	Compaction of flank/slope & raincuts if any	S		
2				
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	_		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S		
c)	Condition of railings/slab/approach for Bridges	NA		
d)	Condition of Vent Clearance	5		
Observa	ation Remarks:-			
3.	Road Furniture	Marie San Company		
a)	Whether sign boards/informatory/cautionary Board/ km & 200m stones/Pavement road markings are provided and maintained	S		
Observa	tion Remarks:-			
4.	Compliance History			
a)	Status of ATR's & any others			
Overall	Rating :			
Ovciali	Catisfactory (S)/ Unsatisfactory (I)	Satisfied		

Satisfactory (S)/ Unsatisfactory (U)

Name of Officer:-		Mahesh	Pd Gupta.
Designature:-	-	OWD R	egional la

purnea.