

R.W.D.(W) Sub Division, Katra (Muzaffarpur)					
NAME OF WORK		Part B Construction of RCC Bridge Span 3x165m in Between PMGSY L 047 to Shiwji Mahto Home at Ch400m			
Sl.No.	Description of Work	Unit	Qty.	Rate per Unit	Amount
1	Supplying, laying & spreading of Brick bats etc. complete job as per specification and direction of E/I.	M <sup>3</sup>	148.75	2064.56 <del>2272.66</del>	307103.30 <del>338058</del>
Grand Total Rs.					<del>338058</del>

Suf Rs 3.07 Lakhs

*[Signature]*  
JE(RWD) Muz. East-2

*[Signature]*  
AE(RWD) Muz. East-2

*[Signature]*  
EE(RWD) Muz. East-2

## GENERAL ABSTRACT

Name of road

Part B Construction of RCC Bridge Span 3x165m in Between  
PMGSY L 047 to Shiwji Mahto Home at Ch400m

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East -2

Lenth of Road( in KM )

SI.NO.	DESCRIPTION	AMOUNT (IN LAKHS)
1	Brick Bats	3.38
2	Sand	3.071
3	Hume Pipe	
GRAND SUB TOTAL		3.38

*dm*  
JE(RWD) Muz. East-2

*11.23.11*  
AE(RWD) Muz. East-2

*9/11/11*  
EE(RWD) Muz. East-2

As Per S.E. RWD (W) Circle Muz.  
Letter No 1179 Dated 01/10/2021  
Estimate has been sanctioned by inspecting  
E.E. RWD, (W) Circle Muz East-1

*Sanctioned*  
*Technically Approved for Rs. 3.071 lakhs*  
*(Rs. Three lakhs seven thousand one hundred)*  
*only (provisionally)*

*24.12.21*  
Superintending Engineer  
Rural Works Department  
Work Circle, Muzaffarpur

## Inspection Report for Flood Damage Work

Date

- 1 Name of PIUs- Gyan vibhaleed
- 2 Name of Block/Road- Katta/Path construction at RCC Bridge 5 bcm 3x16.5m in in between pmgsy 1047 to shiwji maha Home at chak

A For Road

- 1 Damage Location/Chainage 0.
- 2 Damage Length
- 3 Nature of Damage
- 4 Details of Restoration Works-

- i Material being used in Restoration Works-
- ii Equipments/Tools being used in Restoration Works-
- iii Procedure Taken up in Restoration Works-
- iv Restored Length

B For Bridge

- 1 Damage Location/Chainage : 0.250 km to 0.287 km
- 2 Damage Length : 0.0370 km
- 3 Nature of Damage : Flood
- 4 Details of Restoration Works-

- i Material being used in Restoration Works- balck ball - 148.75m<sup>3</sup>  
remedone satisfactory
- ii Equipments/Tools being used in Restoration Works- Tractor
- iii Procedure Taken up in Restoration Works-
- iv Restored Length : 0.0370

Signature of JE/ AE/ EE

Signature

(Name of Inspector)

कार्यपालक अभियंता  
ग्रामीण कार्य विभाग  
कार्य प्रमंडल, मुजफ्फरपुर पूर्व-1