

FA R

2021-22

HB.No- 63

Schedule XLV-Form No. 134

2013 to 2014 till

DIVISION

SUB-DIVISION

Block - Dhamdaha

Measurement Book

Dhamdaha DIVISION

Dhamdaha SUB-DIVISION

50113 'to Hashi' talu

MEASUREMENT BOOK

No. - 63

प्रमाणित किया जाता है कि इस माप
पुस्तक में उद्धृत 1150 वर्ग फुट
माप का अन्त प्रमाणित 46/10/19
वर्ग फुट 5 11/16 इंच 1/2 इंच 1/4 इंच

Name of Officer

205-10-21

Date of first entry **Executive Engineer**
Rural Works Department

Date of last entry **Works Division, Dhamdaha (Pune)**

105/10/17

Sch. XIV—Form No. 134

Particulars	Details of actual measurement				Contents of item
	No.	L.	B.	D.	
NAME OF WORK	F. D. E.				
Measurable Restoration of					
SO 113 To Nabh Tola.					
Agency:-					
(ABSTRACT OF COST)					
1/1 Construction of					
embankment with					
Approved material					
76.8 m ³ Qty vide					
P.O. item No. (61)					
@ 171203 / m ³					
					Rs 131352.

2/2 Providing and laying					
R.C.C. Pipe 1500					
1000 (mm) Qty					
10 meter @ P.O.					
item No. (62) @ 4362					
4362 = 15/meter					
					Rs 436212

3/3 Providing Brick					
bat including					
spreading and laying					
Compacting 147.52 m ³					
Qty vide P.O. (65)					
@ 2188.95 / m ³					
					Rs 322759

Continuation Rs 3,79,515.00

By: 372,515,
14

Particulars	Details of actual measurement				Contents of aroon
	No.	L.	B.	D.	
4-1-A	Lab. 01	For driving			
	(62 mm to 75 mm)				
	680 mtr	Qty			
	vide or P-01	(23)			
	@ 52064/mtr				
					Rs. 35795
5-5	Supply, fitting &				
	fixing of Bamboo				
	152.85 mtr	Qty			
	vide or P-02	(05)			
	@ 30212/mtr				
					Rs. 46042
					Rs. 4,19,9142
Add G.S.T 12%.					(11) 50,3902

Add L.F. Labours cells (+)	41	992w
Add S. Fee ———— (+)	4	8002
Total (+)	4,80,8032	
b. 4,80,8032w		

Kumar
23-12-2022
(J.E.)

23/12/2021
A.E

2-12-21

Continuation

Date: 04.12.21 Inspection Report for flood damage work (year 2021-22)

1. Name of PIUs-

Dhamdaha

2. Name of Block/Road-

Dhamdaha - 50113 to Nashi Tola

A. For Road

1. Damage Location/Chainage : - CH- 2400 Mtr.
2. Damage Length : - 36.5 Mtr.
3. Nature of Damage : - Due to flood.

4. Details of Restoration

- i Material being used in Restoration : - Bamboo, Brick bats
ii Equipment/Tools being used in Restoration works : - 36.5 Mtr.
iii Procedure taken up in Restoration works :
iv Restored Length :

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration :
i Material being used in Restoration :
ii Equipment/Tools being used in Restoration works :
iii Procedure taken up in Restoration works :
iv Restored Length :

P. Kumar
04.12.2021
Signature of JE/AE/EE

A.E.
04/12/2021
A.E.

A.E.
04/12/21
Signature
(Name of Executive Engineer
Rural Works) Division
PURNEA

04.12.21
Executive Engineer,
Rural Works Department
Works Division Dhamdaha (Purnea)

Scanned with CamScanner