

Inspection Report for Flood Damage Works:-

Date :-

1. Name of PIUs - Executive Engineer, RWD, Raxaul
2. Name of Block - Adapur
3. Name of Road - GBC Bhaluwahi chowk to Adapur station

(A) For Road

1. Damage Location/Chainage :- 50-60, 75-78, 110-115, 175-180, 190-200, 255-268
830-890, 320-325, 650-820
2. Damage Length :- 590 M 268.20M
3. Nature of Damage:- Road crust badly Damaged.
4. Details of Restoration Works:- Damaged Road fill by Brick Bats.
 - (i) Material being used in Restoration works: Brick Bats
 - (ii) Equipments/ Tools being used in Restoration works: Tractor
 - (iii) Procedure taken up in Restoration works: Departmentally.
 - (iv) Restored Length: 590 M 268.20M

Satisfactory

Aug
20/04/22
SE

for
20/04/22
SE

Signature
20/04/22
Executive Engineer
RWD, (W) Div. P. C. Mandal

of Work:-

Estimate for Repair of Road breaches (Damaged by Flood) for Motorability in GBC Bhaluwahi Chowk to Adapur Station For year 2021.

FDR Length-0.90KM

Name of Item	unit	No	Length	Width	Height	Qty.	Rate	Amount
Labour for laying dry graded Jhama Khoa or stone filter under Brick Pitching or Boulder Pitching in slope or apron including light ramming etc. all complete as per approved design, specification and direction of E/I.	cum	As Per			Appendix I	297.628	2080.40 1911.02	613229.00 568769.00
TOTAL (in Rs.)								613229.00

Say Rs 613229.00

568800/-

[Signature]

Junior Engineer,
Rural Works Department,
Works Section, Adapur

[Signature]

Assistant Engineer,
Rural Works Department,
Works Sub Division, Adapur

[Signature]

Executive Engineer,
Rural Works Department,
Works Division, Raxaul

fact T A T S is accorded for Rs. 5,68,800.00
(.....) crore. *five* *sixty eight* thousand
Eight hundred only.

[Signature] 18/03/2022
S.E. (R.W.D.)
works Circle
Motihari