

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- EE, RWD, Muzaffarpur Cant-1

2 Name of Block/Road :- <sup>Raychourpore</sup> Gaidhat / <sup>Raychourpore</sup> Chander malik home to  
Shanberg dike main road

### (A) For Road:

1. Damage Location/Chainage :- At many locations
2. Damage Length :- 5200m
3. Nature of Damage :- Potholes of Road
4. Details of Restoration Works :-

- (i) Material being used in Restoration works:- Road Baf (262.8243)
- (ii) Equipment's/Tools being used in Restoration works:- JCB, Grader, Road Roller
- (iii) Procedure taken up in Restoration works:- Immediate restoration of traffic
- (iv) Restored Length :- 5200m

### (B) For Bridge:

The work found satisfactory

1. Damage Location/Chainage :-
  2. Damage Length :-
  3. Nature of Damage :-
  4. Details of Restoration Works :-
- (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

NA  
1

  
Signature of JE/AE/EE

  
24/11

  
Signature

(Name of Inspection)

Er. Gyan Bisshaker

(EE, RWD, Muzaffarpur Cant-1)

Raghu pur Pm 417

**GENERAL ABSTRACT**

Name of Road ^ Ramchandar Malik House to Dhanwara Dih Main Road

District Muzaffarpur

Block GAIGHAT

Division Muzaffarpur East-2

Length of Road (in Km)

Sl no	DESCRIPTION	AMOUNT (LAKHS)
1	Brick-Bats	542608 - 587344.88
	GARAND SUB TOTAL	542608 - 587344.88
TOTAL COST OF PROJECT IN LACS=		542608 587345.00

820/11/11/11  
S.E

Raghu pur Pm 417  
A.E

26/12/21  
say 5.43 lacs

As Per S.E. RWD (W) Circle Muz.  
Letter No 1179 dated 01/10/2021  
Estimate has been verified by inspecting  
E.E RWD. (W) Division Muz. East-1

Technically Sanctioned for Rs. 5.43 lacs (Rs. Five  
lacs forty three thousand) only (provisionally)

26/12/21  
Superintending Engineer  
Rural Works Department  
Work Circle, Muzaffarpur  
24.12.21