Inspection Report for flood Damage Work

Date:	-	THE PROPERTY OF THE PROPERTY O
1-	Name of PIU	S :- R.W.D., (W) Division, Chapra - II
2-	Name of Bloo	ck/Road: Dence bur
A,	1- Dams 2- Dams	ck/Road: - Dence bur Shyamkan riya to chapyer Rath nge Location/Chainage: - B+km (chee. 0.4m, 0.6m, 0.9c nge Length: 0.430 km c of Damage: Plank and Room Cont
	4- Detail	s of Restoration :-
	i-	Material being used in Restoration
	ii-	Equipment/Tools being used in Restoration Works :- *
	iii-	Procedure taken up in Restoration Works :- 1
	iv-	Restored Length :-

B. FOR BRIDGE

- 1- Damage Location/Chainage
- 2- DAmage Length
- 3- Nature of Damage
- 4- Details of Restoration
 - i-Material being used in Restoration
 - Equipment/Tools being used in Restoration Works ii-
 - Procedure taken up in Restoration Works iii-
 - iv-Restored Length

Signature poste AE/E

(Name of Inspector) R W. D., (W) Division

Chapra-1