

Inspection Report for flood Damage Work

Date :-

1- Name of PIUs :- R.W.D., (W) Division, Chapra - II

2- Name of Block/Road :-

Isnaipur
Gaudar to Prathmic Gadhri

A. FOR ROAD

1- Damage Location/Chainage :- 2nd km (1.50 to 2.20 km)

2- Damage Length :- 0.480 km.

3- Nature of Damage :- flank and Road crest due to flood.

4- Details of Restoration :-

i- Material being used in Restoration :-

ii- Equipment/Tools being used in Restoration Works :-

iii- Procedure taken up in Restoration Works :- 1

iv- Restored Length :-

B. FOR BRIDGE

1- Damage Location/Chainage :-

2- Damage Length :-

3- Nature of Damage :-

4- Details of Restoration :-

i- Material being used in Restoration :-

ii- Equipment/Tools being used in Restoration Works :-

iii- Procedure taken up in Restoration Works :-

iv- Restored Length :-

Signature of JEAAE/EE
JE

19.11.21
R.E

Signature
Executive Engineer
(Name of Inspector),
Chapra-1