Inspection Report for Flood Damage Works:-

¥		ip.	*	.ee	-	
-1	ð,	A	Ę	U	Ŷ,	9.

					O- vaul	
1.	Name of PIUs -	Executive	Engineer,	RWD.	WEIKHING.	Leeses

2. Name of Block - Rom gartwa

3. Name of Road - Pakhanda chack - Jaitapur Puth

(A) For Road

	Damage Location/Chainage :-		7402	3952-3956
1.	Damage Location/Chainage :-	3935-3945,	3995-33321	

- 2. Damage Length :- 51 M
- 3. Nature of Damage: Road Crist damoged.
- Details of Restoration Works:-
 - (i) Material being used in Restoration works: Bolck Bak
 - (ii) Equipments/ Tools being used in Restoration works: Tracker
 - (iii) Procedure taken up in Restoration works: Deportmental.

(iv) Restored Length: 5/ M

satus Factory

1910/101

18/20/20

Executive Engineer RWD, (W) Div. P.A.K.A. Dalen me of Work:

Estimate for Repair of Road breaches (Damaged by Flood) for Motoribility in Pakhania Chaok - Jaitapur Path (BR-11-07C) For year 2021.

FDR Length-4.00KM Name of Item	1	2	G	69	teight	Ė	Rate	Imount
Labour for laying dry graded Jhama Khoa or stone filter under Brick Pitching or Boulder Pitching in slope or apron including light ramming etc. all complete as per approved design, specification and direction of E/L.				Per ndix I		157.778	2060.40	32508800
						TOT	AL (in Rs.)	325086.00
					S	ay Rs	325086.00	1

Junior Engineer, urai Works Department, urks Section, Ramgarhwa

Assistant Engineer, Rural Works Department, Works Sub Division, Ramgarhwa Executive Engineer Rural Works Department, Works Division, Raxaul

Post facto TATS is accorded for Rs. 3,01,500 Do To To Crore Proper lacs Oul thousand hundred jorty.

B.E. (R.W.O.* works Circle Motihari