Inspection Report for Flood Damage Works:-

Date:-

- 1. Name of PIUs Executive Engineer, RWD, ... RANGUM.....
- 2. Name of Block Rangashwa
- 3. Name of Road LO39 LO26 Seithbena Khugni

(A) For Road

- 52-61, 75-78, 80-87, 112-126, 135-138 Damage Location/Chainage :-1.
- 34.6 M Damage Length 2.
- Nature of Damage: Road Crust damogid. 3.
- Details of Restoration Works:- Brick Bass Jilly 4.
 - (i) Material being used in Restoration works: Brick Bak
 - (ii) Equipments/ Tools being used in Restoration works: Toucher
 - (iii) Procedure taken up in Restoration works: Deportmental.

(iv) Restored Length: 34.6 M

Saturactory

A 1910/12 12/07/2

Name of Work:-

Estimate for Repair of Road breaches (Damaged by Flood) for Motoribility in L039- L026 SEIKHBENA -KHUGNI (BR-11R-422) Road For year 2021.

	Head -		FDR Length-2 KM									
SN IS		Item No.	Name of Item	unit	№	Length	Width	Height	Otty.	Rate	Amount	
			Labour for laying dry graded Jhama Khoa or stone filter under Brick Pitching or Boulder Pitching in slope or apron including light ramming etc. all complete as per approved design, specification and direction of E/I.				Per Indix I		19.470	2060.40 1911 · O	49145.00 37201	,5!
L	_		×						T	OTAL (in Re.)	40115.00	

Rural Works Department, Works Section, Ramgarhwa

Assistant Engineer, Rural Works Department, Works Sub Division, Ramgarhwa

Exegutive Enginee Rural Works Department, Works Division, Raxaul

Say Rs

TAITS is accorded for Rs......

SE (RWE) Works Circle

Motihari