

# INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS
2. Name of Block/Road

R.W.D works Division Harnaut  
:- Harnaut :- Hirdan bigha to Ilampur Mushe

## A. For Road :

1. Damage Location/Change :- CH-100M
2. Damage Length :- 14M ✓
3. Nature of Damage :- Plank Damage
4. Details of Restoration Works :- Bamboo, sand bags filling bamboo.
  - i. Material Being used in Restoration works :- Bamboo, sand bags, empty car
  - ii. Equipment's / Tools being used in Restoration works :- Tractors, J.C.B,
  - iii. Procedure taken up in restoration works :-
  - iv. Restored Length :-

## B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - i. Material Being used in Restoration works :-
  - ii. Equipment's / Tools being used in Restoration works :-
  - iii. Procedure taken up in restoration works :-
  - iv. Restored Length :-


## C. Requirement of New CD/Bridge :

- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-


- Upload one photograph of damaged portion if available
- 
- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

Signature of

  
JE

  
AE

  
EE

  
Executive Engineer  
Rural Works Department  
Works Division, Rajgi