

Inspection Report for Flood Damage work

Date:-

1 Name of PIUS :-

2 Name of Block :-

3 Name of Road :-

Madhepura

Murhiganr

Ragunathpur ward no-6 me Kameshwar Yadhar ke Ghar se
Kailash Yadhar ke Ghar tak

A. For Road

1 Damage Location/Chainage :-

2 Damage Length :-

0.750 km

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

Bricks bats, local sand

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

A. Kumar
01/11/21
JE

Prakash
01/11/21
AE

EE

01/11/21

Signature

(Name of inspector)

Schedule XLV-Form No. 134

Madhepura

DIVISION

Muzaffarpur

SUB-DIVISION

Rafinhatpur ward no-6 Me Kameghwar Yadav ke Sakhar
Se Kailash Yadav ke Sakhar

Measurement Book

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
367 to 459	3	30	3.00	0.45	122.71
	1	1.50	2.74	0.30	1.23
459 to 550	3	30	3.15	0.40	113.40
	1	1.5	3.25	0.35	1.96
550 to 700	1	30	3.10	0.30	27.90
	1	1.6	3.00	0.350	16.80
					694.18
item-2 Sand Filling in furnch					
	15	30	2.59	0.075	87.41
	1	23	2.59	0.075	4.46
	1	20	4.5	0.450	40.50
	1	13.2	4.5	0.450	26.75
	1	16	4.5	0.450	32.40
	1	13	4.5	0.450	26.32
					217.85
Abstract of Gyl					
providing and laying of Bricks, but					
V.T.M.B.P. No-(1)					
item no (1) — 694.18 M ³					
to 1922.87/M ³ — 1334818=					
(2/1) Sand Filling in furnch					
V.T.M.B.P. No-(2)					
item no (2) — 217.85 M ³					
to 582.71/M ³ — 126943=					
					14, 61, 761=

Continuation

