Inspection Report For Flood Damage Work

Date: - 21.11.2021

1. Name of PIUs: - Er Bifay Kumar.

2. Name of Block/Road: - Rahui/anst of R.C. C Bn'dge on Panchane River Near willay or Road

Dihra in Bhaganbigha Rahw' Road

A. For Road

- 1. Damage Location/Chainage :- 480 To SSO ut
- 2. Damage Length :- 34.50 wtr
- 3. Nature of Damage :- crust and flank,
- 4. Details of Restoration Works:
 - i. Material being used in Restoration Works:- Brick Bats and R-S-B
 - Equipments/ Tools being used in Restoration Works:-J.c.B, Roller and Tractor ii.
 - Procedure taken up in Restoration Works:- Defortmental
 - Restored Length: 34,50 utr. iv.

B. For Bridge

- 1. Damage Location/Chainage:-
- 2. Damage Length:-
- 3. Nature of Damage:-
- 4. Details of Restoration Works:-
 - Material being used in Restoration Work:-
 - Equipments/ Tools being used in Restoration Works:ii.
 - Procedure taken up in Restoration Works:iii.
 - Restored Length:-
- Requirement Of New CD/Bridge C.
 - Name of Road:-
 - Location Chainage:ii.
 - Type of CD Work/Length Required iii.

Upload one photograph of damage portion if available

Attach minium two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

Signature of verifying officer

NA .