

Inspection Report For Flood Damage Work

Date :-

1. Name of PIUs :- En. Bijay Kumar
2. Name of Block/Road :- Samra/Rampur-Badhi Chharizari to SH 78

A. For Road

1. Damage Location/Chainage :-
2. Damage Length :- 13.00 Meter
3. Nature of Damage :- crust damage
4. Details of Restoration Works :-
 - i. Material being used in Restoration Works:- C.S.B
 - ii. Equipments/ Tools being used in Restoration Works:- JCB, Tractor & Bol
 - iii. Procedure taken up in Restoration Works:- Departmental
 - iv. Restored Length:- 13.00 Meter.

B. For Bridge

1. Damage Location/Chainage:-
2. Damage Length:-
3. Nature of Damage:-
4. Details of Restoration Works:-
 - i. Material being used in Restoration Work:-
 - ii. Equipments/ Tools being used in Restoration Works:-
 - iii. Procedure taken up in Restoration Works:-
 - iv. Restored Length:-


C. Requirement Of New CD/Bridge


- i. Name of Road:-
- ii. Location Chainage:-
- iii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode


Signature of JE/AE/EE


Signature of verifying officer