

Inspection Report For Flood Damage Work

Date :- 25-11-2021

1. Name of PIUs :- Er. Bijay Kumar

2. Name of Block/Road :- Biharsarif / Manduwa to Singher via Chhabilapur

A. For Road

1. Damage Location/Chainage :- 3.20 to 3.25 Km.

2. Damage Length :- 13.0 m.

3. Nature of Damage :- Crust Flank & Breaches

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- Brick Bat, Hum Pipe & G.I.

ii. Equipments/ Tools being used in Restoration Works:- JCB, Tractor & Roller

iii. Procedure taken up in Restoration Works:- Departmental

iv. Restored Length:- 13.0 m.

B. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

NA

C. Requirement Of New CD/Bridge

i. Name of Road:- ~~Manduwa to Singher~~

ii. Location Chainage:-

iii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

Signature of JE/AE/EE
25/11/21

Signature
25/11/21

Signature of verifying officer