

Inspection Report For Flood Damage Work

Date :- 25/11/2024

1. Name of PIUs :- En. Bijay Kumar

2. Name of Block/Road :- Samara/ L024 - Dhanawan Pih To Kayichak

A. For Road

1. Damage Location/Chainage :-

2. Damage Length :- 21.00 Meter

3. Nature of Damage :- Breach/Crust Damage.

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- Bricks Best d. G.S.B

ii. Equipments/ Tools being used in Restoration Works:- JCB, Tractor & Reu.

iii. Procedure taken up in Restoration Works:- Departmental

iv. Restored Length:- 21.00 meter

B. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

ND

C. Requirement Of New CD/Bridge

i. Name of Road:-

ii. Location Chainage:-

iii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

25/11/24
28

Signature of JE/AE/EE

Signature of verifying officer