

# Inspection Report For Flood Damage Work

Date :- 25/11/21

1. Name of PIUs :- En. Bijay Kumar

2. Name of Block/Road :- Ramnagar/LOSS To G to Bari Adwari (VR 24)

## A. For Road

1. Damage Location/Chainage :-

2. Damage Length :- 31.00 meter

3. Nature of Damage :- Flank, Crust & Breach

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- Bricks, Bats & C.C.B

ii. Equipments/ Tools being used in Restoration Works:- JCB, Roller & Tractor

iii. Procedure taken up in Restoration Works:- Departmental

iv. Restored Length:- 31.00 meter

## B. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

## C. Requirement Of New CD/Bridge

i. Name of Road:-


ii. Location Chainage:-


iii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

  
Signature of JE/AE/EE

  
Signature of verifying officer