

Inspection Report For Flood Damage Work

Date :- 21/11/2021

1. Name of PIUs :- E. B. Jay Kumar

2. Name of Block/Road :- Rahmi / Toh saidi more to Basak saidi

A. For Road

1. Damage Location/Chainage :- 00 To 2.640 Km

2. Damage Length :- 0.207 Km

3. Nature of Damage :- Crest and flank

4. Details of Restoration Works :-

i. Material being used in Restoration Works :- GSB, Brick Bat and Sand bag

ii. Equipments/ Tools being used in Restoration Works :- JCB, Roller and Fract

iii. Procedure taken up in Restoration Works :- Departmental

iv. Restored Length :- 0.207 Km

B. For Bridge

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works :-

i. Material being used in Restoration Work :-

ii. Equipments/ Tools being used in Restoration Works :-

iii. Procedure taken up in Restoration Works :-

iv. Restored Length :-

NA

C. Requirement Of New CD/Bridge

i. Name of Road :-


ii. Location Chainage :-

iii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode


21/11/21
812

Signature of JE/AE/EE


21.11.2021

Signature of verifying officer