

# Inspection Report For Flood Damage Work

Date :- 25/11/21

1. Name of PIUs :- En. Bijay Kumar.
2. Name of Block/Road :- Baid/5478 to Kishar.

## A. For Road

1. Damage Location/Chainage :- 1600 to 1700 meter.
2. Damage Length :- 43.50 meter.
3. Nature of Damage :- Breach & crack.
4. Details of Restoration Works :-
  - i. Material being used in Restoration Works:- Bricks Bat & G.S.R
  - ii. Equipments/ Tools being used in Restoration Works:- SEB, Roller & tractor
  - iii. Procedure taken up in Restoration Works:- Departmental
  - iv. Restored Length:- 43.50 meter.

## B. For Bridge

1. Damage Location/Chainage:-
2. Damage Length:-
3. Nature of Damage:-
4. Details of Restoration Works:-
  - i. Material being used in Restoration Work:-
  - ii. Equipments/ Tools being used in Restoration Works:-
  - iii. Procedure taken up in Restoration Works:-
  - iv. Restored Length:-


## C. Requirement Of New CD/Bridge


- i. Name of Road:-
- ii. Location Chainage:-
- iii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

  
Signature of JE/AE/EE

  
Signature of verifying officer