

# Inspection Report For Flood Damage Work

Date :- 25.11.2021

1. Name of PIUs :- Er Bijay Kumar.

2. Name of Block/Road :- Rahui/NH-31 To Pachosa village Through Rajwan Tola

## A. For Road

1. Damage Location/Chainage :- 12.00 to 20.00 mtr.

2. Damage Length :- 2.00 mtr.

3. Nature of Damage :- crust and flank.

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- Brick Bats.

ii. Equipments/ Tools being used in Restoration Works:- J.C.B and Tractor

iii. Procedure taken up in Restoration Works:- Departmental

iv. Restored Length:- 2.00 mtr.

## B. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

NA.

## C. Requirement Of New CD/Bridge

i. Name of Road:-


ii. Location Chainage:-


iii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

  
25.11.21  
Signature of JE/AE/EE

  
25.11.21  
Signature of verifying officer