

Inspection Report For Flood Damage Work

Date :- 25/11/2021

1. Name of PIUs :- Bn. Bijay Kumar
2. Name of Block/Road :- Bind / Benar - Sakshra Road To Tarnipur

A. For Road

1. Damage Location/Chainage :- 850 to 900 meter,
2. Damage Length :- 21.00 meter,
3. Nature of Damage :- Breach & crust.
4. Details of Restoration Works :-
 - i. Material being used in Restoration Works:- Bricks Batts.
 - ii. Equipments/ Tools being used in Restoration Works:- JCB Tractor & Roller
 - iii. Procedure taken up in Restoration Works:- departmental
 - iv. Restored Length:- 21.00 meter,

B. For Bridge

1. Damage Location/Chainage:-
2. Damage Length:-
3. Nature of Damage:-
4. Details of Restoration Works:-
 - i. Material being used in Restoration Work:-
 - ii. Equipments/ Tools being used in Restoration Works:-
 - iii. Procedure taken up in Restoration Works:-
 - iv. Restored Length:-

C. Requirement Of New CD/Bridge

- i. Name of Road:-
- ii. Location Chainage:-
- iii. Type of CD Work/Length Required

NO

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode.

(11)
25/11/21
7/12

25/11/21

25/11/21

25.11.21

Signature of JE/AE/EE

Signature of verifying officer