

Inspection Report For Flood Damage Work

Date :- 25/11/21

1. Name of PIUs :- Arjay Kumar
2. Name of Block/Road :- Ashawan / KIH 82 Kundhari - Sarbahi - to
Will - Piprahar

A. For Road

1. Damage Location/Chainage :- 90 to 100 Meter
2. Damage Length :- 2.00 Meter
3. Nature of Damage :- Crack Berach
4. Details of Restoration Works :-
 - i. Material being used in Restoration Works :- Bricks Bat
 - ii. Equipments/ Tools being used in Restoration Works :- JCB & Tractor
 - iii. Procedure taken up in Restoration Works :- Departmental
 - iv. Restored Length :- 2.00 Meter

B. For Bridge

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material being used in Restoration Work :-
 - ii. Equipments/ Tools being used in Restoration Works :-
 - iii. Procedure taken up in Restoration Works :-
 - iv. Restored Length :-

C. Requirement Of New CD/Bridge

- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

25/11/21

Signature of JE/AE/EE

25/11/21
Signature of verifying officer