## Inspection Report For Flood Damage Work

Date: - 21.11.2021

1. Name of PlUs :- er Bifoy kumar.

2. Name of Block/Road :- Rahmi/ Rahimpur foot over Bridge To Gobarija will A. For Road

1. Damage Location/Chainage: - 0.00 to 175.19 utr.

2. Damage Length :- 12.50 utr

3. Nature of Damage :- Crust an I flank.

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- Brick Bods.

ii. Equipments/ Tools being used in Restoration Works:- J.C.B and Fractor.

iii. Procedure taken up in Restoration Works:- De Partmental

iv. Restored Length:- 12.50 utr.

## B. For Bridge

- 1. Damage Location/Chainage:-
- 2. Damage Length:-
- 3. Nature of Damage:-
- 4. Details of Restoration Works:
  - i. Material being used in Restoration Work:-
  - ii. Equipments/ Tools being used in Restoration Works:-
  - iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

## C. Requirement Of New CD/Bridge

i. Name of Road:-

ii. Location Chainage:-

ii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minium two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

Signature of JE/AE/EE

3111227

Signature of verifying officer

NA