

# Inspection Report For Flood Damage Work

Date :- 25/11/2021

1. Name of PIUs :- En. Bijay Kumar

2. Name of Block/Road :- Bind/ Pulhanpur to Bakra to Makempu

## A. For Road

1. Damage Location/Chainage :- 1000 to 1.600meters.

2. Damage Length :- 130.50 Meter

3. Nature of Damage :- Breach & crust.

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- Bricks Bat & GSB

ii. Equipments/ Tools being used in Restoration Works:- JCB, tractor, Roll.

iii. Procedure taken up in Restoration Works:- departmental

iv. Restored Length:- 130.50 meter.

## 3. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

## C. Requirement Of New CD/Bridge

i. Name of Road:-

ii. Location Chainage:-

iii. Type of CD Work/Length Required

NA

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

25/11/21  
Signature of JE/AE/EE

25/11/21  
Signature of JE/AE/EE

25/11/21  
Signature of verifying officer