Inspection Report For Flood Damage Work

Date: 25/11/2029

1. Name of PIUs: - Er. Bijay Kurnar

2. Name of Block/Road: Bind/ Soiba Alipur Road (SH-78) to r Road

Darryapur South.

A. For Road

1. Damage Location/Chainage of 0 to Loo Meter.

2. Damage Length:-

·41.00 Meter.

3. Nature of Damage:-

Flace, anucht & Breach.

4. Details of Restoration Works:-

Material being used in Restoration Works: Bride Bat & C. 13.

Equipments/Tools being used in Restoration Works:- JCB Tractor, & Rouce ii.

Procedure taken up in Restoration Works: Departmental iii.

41.00 metul Restored Length:iv.

. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

Material being used in Restoration Work:i.

Equipments/ Tools being used in Restoration Works:ii.

Procedure taken up in Restoration Works:iii.

Restored Length:iv.

Requirement Of New CD/Bridge C.

> Name of Road:i.

Location Chainage:ii.

Type of CD Work/Length Required iii.

Upload one photograph of damage portion if available

Attach minium two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

Signature of verifying officer

Scanned with CamScanner

NA