

Inspection Report For Flood Damage Work

Date :- 21.11.2021

1. Name of PIUs :- Er Bijay Kumar.

2. Name of Block/Road :- Rahui/ To1 To Ganjpar.

A. For Road

1. Damage Location/Chainage :- 0.00 to 30.00 mtr.

2. Damage Length :- 30.00 mtr.

3. Nature of Damage :- Crust and flank.

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- Brick Bats and G.S.B

ii. Equipments/ Tools being used in Restoration Works:- J.C.B, Roller and Tractor

iii. Procedure taken up in Restoration Works:- Departmental

iv. Restored Length:- 30.00 mtr

B. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

C. Requirement Of New CD/Bridge

i. Name of Road:-

ii. Location Chainage:-


iii. Type of CD Work/Length Required


NA

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode


21.11.21
Signature of JE/AE/EE


21.11.21
Signature of verifying officer