

Inspection Report For Flood Damage Work

Date :- 25.11.2021

1. Name of PIUs :- er Bijay Kumar

2. Name of Block/Road :- Rahui/Biharnigay Road in Mathurapur To Farida

A. For Road

1. Damage Location/Chainage :- 3.00 KM to 5.80 KM

2. Damage Length :- 173.10 mtr.

3. Nature of Damage :- crust and flank.

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- Brickbats and G.S.B

ii. Equipments/ Tools being used in Restoration Works:- JCB, roller and tractor

iii. Procedure taken up in Restoration Works:- Departmental.

iv. Restored Length:- 173.10 mtr.

3. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

Requirement Of New CD/Bridge

i. Name of Road:-

ii. Location Chainage:-

iii. Type of CD Work/Length Required

NA

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

K. S. S. S.
25.11.21

Signature of JE/AE/EE

25.11.21

Signature of verifying officer