

Inspection Report For Flood Damage Work

Date :- 25/11/2021

1. Name of PIUs :- Ex. Bisay Kumar

2. Name of Block/Road :- Rahui / NH 31 Dhamauli to Bihar Hifay Road
Khisaura via Mubarakpur

For Road

1. Damage Location/Chainage :- 4.60km TO 5.20km and 8.60km to 9.50km

2. Damage Length :- 74.40 meter

3. Nature of Damage :- crust and flank

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- GSB and Brick Bat

ii. Equipments/ Tools being used in Restoration Works:- JCB, Roller and Tractor

iii. Procedure taken up in Restoration Works:- Departmental

iv. Restored Length:- 74.40 meter

3. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

Requirement Of New CD/Bridge

i. Name of Road:-

ii. Location Chainage:-

iii. Type of CD Work/Length Required

NA

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

31/11/21
8E

25/11/21

25/11/21

Signature of JE/AE/EE

25/11/21

Signature of verifying officer