

# Inspection Report For Flood Damage Work

Date :- 25/11/2021

1. Name of PIUs :- Er. Bifay Kumar

2. Name of Block/Road :- Rahmy CO38 To Beshorak

## A. For Road

1. Damage Location/Chainage :- 00 to 40 meter

2. Damage Length :- 32 meter

3. Nature of Damage :- Flank

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- Brick Bat

ii. Equipments/ Tools being used in Restoration Works:- JCB and Tractor

iii. Procedure taken up in Restoration Works:- Departmental

iv. Restored Length:- 32 meter

## B. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

## C. Requirement Of New CD/Bridge

i. Name of Road:-

ii. Location Chainage:-

iii. Type of CD Work/Length Required

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

Signature of JE/AE/EE  
25/11/21  
32

Signature of verifying officer  
25.11.2021