

Inspection Report For Flood Damage Work

Date :- 21.11.2021

1. Name of PIUs :- *Er Brijay Kumar.*

2. Name of Block/Road :- *Rahui/Rahui Mahadipur ke kona To Dulchandpur will*

A. For Road

1. Damage Location/Chainage :- *100 to 695.10 mtr.*

2. Damage Length :- *48.80 mtr.*

3. Nature of Damage :- *crust and flank.*

4. Details of Restoration Works :-

i. Material being used in Restoration Works:- *Brickbat and sand bag.*

ii. Equipments/ Tools being used in Restoration Works:- *J.C.B and Tractor*

iii. Procedure taken up in Restoration Works:- *Departmental*

iv. Restored Length:- *48.80 mtr.*

B. For Bridge

1. Damage Location/Chainage:-

2. Damage Length:-

3. Nature of Damage:-

4. Details of Restoration Works:-

i. Material being used in Restoration Work:-

ii. Equipments/ Tools being used in Restoration Works:-

iii. Procedure taken up in Restoration Works:-

iv. Restored Length:-

Requirement Of New CD/Bridge

i. Name of Road:-

ii. Location Chainage:-

iii. Type of CD Work/Length Required

NA.

Upload one photograph of damage portion if available

Attach minimum two photograph (during restoration & after restoration) photographs

Should be Geotags and at least one photo be captured in selfie mode

Ksingh
21.11.21
AB
21.11.21
AB
21.11.21

Signature of JE/AE/EF

Inf
21.11.2021

Signature of verifying officer