

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS
2. Name of Block/Road

RWD Works Division Harnaut
Chandi/Motorable of Road from Dandi Harnau
NH 30A Chauspur to Satha.

A. For Road :

1. Damage Location/Change :- 48m
2. Damage Length :- 3.00m
3. Nature of Damage :- Due to excess Rainfall.
4. Details of Restoration Works :-

- i. Material Being used in Restoration works :- GSB material
- ii. Equipment's / Tools being used in Restoration works :- Tractor, Trulli @ JCB etc
- iii. Procedure taken up in restoration works :- GSB used in shoulders / Flank ne
- iv. Restored Length :- 6.50m

Roller

used in shoulders / Flank ne
Bridge

Prm
25/11/21

B. For Bridge :


1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-


C. Requirement of New CD/Bridge :


- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-

- Upload one photograph of damaged portion if available
-
- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode.

Signature of


25/11/21
JE


25-11-21
AE


25-11-2021
EE

Prm
25/11/21
E.E.
R.W.D. Rajgiri