

# INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS
2. Name of Block/Road

RWD Works Division Haranaut.  
Chandi/Motorable of Road from Pmnsy Path,  
to Gram Te Ka Bigha.

## A. For Road :

1. Damage Location/Change :- 330m
2. Damage Length :- 3.00m
3. Nature of Damage :- Due to excess Rainfall.
4. Details of Restoration Works :-
  - i. Material Being used in Restoration works :- G7.3B Material
  - ii. Equipment's / Tools being used in Restoration works :- Tractor, Tooli, JCB, etc
  - iii. Procedure taken up in restoration works :- G7.3B material used in Road Carriage
  - iv. Restored Length :- 3.00m

25/11/24

## B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - i. Material Being used in Restoration works :-
  - ii. Equipment's / Tools being used in Restoration works :-
  - iii. Procedure taken up in restoration works :-
  - iv. Restored Length :-

## C. Requirement of New CD/Bridge :

- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-

- Upload one photograph of damaged portion if available
- 
- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode.

Signature of

JE

AE

EE

25/11/24  
B. E.

L. W. D. Rajis