

# INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R.W.D works Division Harnaut
2. Name of Block/Road :- Harnaut NH30A To poari Kharathua

## A. For Road :

1. Damage Location/Change :- 100m ch.
2. Damage Length :- 3.0m
3. Nature of Damage :- Roadway Damage
4. Details of Restoration Works :- G.S.B filling
  - i. Material Being used in Restoration works :- G.S.B
  - ii. Equipment's / Tools being used in Restoration works :- Tractor, Roller, etc.
  - iii. Procedure taken up in restoration works :- G.S.B material used in Road way.
  - iv. Restored Length :-

## B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - i. Material Being used in Restoration works :-
  - ii. Equipment's / Tools being used in Restoration works :-
  - iii. Procedure taken up in restoration works :-
  - iv. Restored Length :-

## C. Requirement of New CD/Bridge :

- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-

- Upload one photograph of damaged portion if available


•


- Attach minimum two photograph (during restoration & after restoration) photographs should Geotags and at least one photo be captured in selfie mode.

Signature of

  
JE

  
AE

  
EE

  
22/11/21

Executive Engineer  
of Works Department  
Harnaut, Raj