

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R.W.D. works Division Harnaut
2. Name of Block/Road :- Nagarnausa - RWD Road under Bualhakh Panchayat from Harnaut block Road to PWD Road via Balwa Kharjama.

A. For Road :

1. Damage Location/Change :- AT CH-4320M.
2. Damage Length :- 6.50M.
3. Nature of Damage :- Plank Damage
4. Details of Restoration Works :- Sand bags filling, with bamboo piling
 - i. Material Being used in Restoration works :- Sand, empty cement bags & b.
 - ii. Equipment's / Tools being used in Restoration works :- Tractors, bamboo, J.C.B.
 - iii. Procedure taken up in restoration works :- G.S.B Gr II material used
 - iv. Restored Length :- in Road in Carriage width.

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-

C. Requirement of New CD/Bridge :


- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-


- Upload one photograph of damaged portion if available

•


- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode.

Signature of


JE


AE


EE


Executive Engineer
Rural Works Department
Works Division, Rajgir