

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R.W.D. Works Division Harnaut
2. Name of Block/Road :- Harnaut :- Hirdan bigha to Ilampur Mushe

A. For Road :

1. Damage Location/Change :- CH-100M
2. Damage Length :- 14M ✓
3. Nature of Damage :- Flank Damage
4. Details of Restoration Works :- Bamboo, sand bags filling bamboo.
 - i. Material Being used in Restoration works :- Bamboo, sand bags, empty car
 - ii. Equipment's / Tools being used in Restoration works :- Tractors, J.C.B.
 - iii. Procedure taken up in restoration works :- Sand bag used in Road
 - iv. Restored Length :- Embankment.

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-


C. Requirement of New CD/Bridge :


- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-


- Upload one photograph of damaged portion if available


- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

Signature of


JE


AE


EE


Executive Engineer
Rural Works Department
Works Division, Rajgi