

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R.W.D works Division Harnaut
2. Name of Block/Road :- Harnaut :- Gram panchayat Brah to Borah parwah an Road.

A. For Road :

1. Damage Location/Change :- CH-750 M.
2. Damage Length :- 40 M.
3. Nature of Damage :- Plank Damage
4. Details of Restoration Works :- Brick bats filling, bamboo, sand bags
 - i. Material Being used in Restoration works :- Brick bat, bamboo, sand bags
 - ii. Equipment's / Tools being used in Restoration works :- Tractor, J-C-B, etc.
 - iii. Procedure taken up in restoration works :- Brick bats used in Road Carriage in 1.50 m wide
 - iv. Restored Length :-

B. For Bridge :

1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-


C. Requirement of New CD/Bridge :


- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-


- Upload one photograph of damaged portion if available


- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode.

Signature of


JE


AE


EE


Executive Engineer
Rural Works Department
Works Division, Rajgir