

# INSPECTION REPORT FOR FLOOD DAMAGE WORKS

Date :

1. Name of PIUS :- R.W.D WORKS Division Harnaut.
2. Name of Block/Road :- Harnaut - NH304 Baharainpur chattri Road to Abbanmahmadpur R.W.D Rec.

## A. For Road :

1. Damage Location/Change :- <sup>AT</sup> CH- 44M, 470M, 610M, 730M, 920M
2. Damage Length :- Total - 48.0M ✓
3. Nature of Damage :- Flank Damage
4. Details of Restoration Works :- Sand bags
  - i. Material Being used in Restoration works :- Sand, Cement empty bags,
  - ii. Equipment's / Tools being used in Restoration works :- Tractor, J.C.B.
  - iii. Procedure taken up in restoration works :- Sand bag used in Flank in Road Damage.
  - iv. Restored Length :-


## B. For Bridge :


1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - i. Material Being used in Restoration works :-
  - ii. Equipment's / Tools being used in Restoration works :-
  - iii. Procedure taken up in restoration works :-
  - iv. Restored Length :-


## C. Requirement of New CD/Bridge :


- i. Name of Road :-
  - ii. Location Chainage :-
  - iii. Type of CD work/Length required :-
- Upload one photograph of damaged portion if available
  - Attach minimum two photograph (during restoration & after restoration) photographs Geotags and at least one photo be captured in selfie mode.

Signature of

  
JE

  
AE

  
EE

  
Executive  
Rural Works  
Works Div