

INSPECTION REPORT FOR FLOOD DAMAGE WORK

Date :

1. Name of PIUS :- R. W. D Works Division Harnaut.
2. Name of Block/Road :- Harnaut - PMHSY Harnaut to Jalgo bind path village

A. For Road :

1. Damage Location/Change :- CH. 1.80 Km
2. Damage Length :- 26m ✓
3. Nature of Damage :- Plank Damage
4. Details of Restoration Works :- Brick Bat Filling
 - i. Material Being used in Restoration works :- Brick bats
 - ii. Equipment's / Tools being used in Restoration works :- Tractor, J.C.B. Roller Etc
 - iii. Procedure taken up in restoration works :- G.S.B material used in Road in carriage width.
 - iv. Restored Length :-

B. For Bridge :


1. Damage Location / Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - i. Material Being used in Restoration works :-
 - ii. Equipment's / Tools being used in Restoration works :-
 - iii. Procedure taken up in restoration works :-
 - iv. Restored Length :-


C. Requirement of New CD/Bridge :


- i. Name of Road :-
- ii. Location Chainage :-
- iii. Type of CD work/Length required :-


- Upload one photograph of damaged portion if available
-
- Attach minimum two photograph (during restoration & after restoration) photographs should be Geotags and at least one photo be captured in selfie mode

Signature of


JE


AE


EE


22/11/24

Executive Engineer
Rural Work Department
Works Division, Rajgir