

# Inspection Report for Flood Damage Works:-

Date :-

1. Name of PIUs – Executive Engineer, RWD, Raxaul.....
2. Name of Block – Adepur
3. Name of Road – Labhaura - Adepur RED Road to Bheniyahi

## (A) For Road

1. Damage Location/Chainage :- 735-746, 815-822, 830-836, 1321-1350
2. Damage Length :- 37 M
3. Nature of Damage:- Road crust Damaged.
4. Details of Restoration Works:- Brick Bats Filling in damaged locations.
  - (i) Material being used in Restoration works: Brick Bats
  - (ii) Equipments/ Tools being used in Restoration works: Tractor
  - (iii) Procedure taken up in Restoration works: Departmental.
  - (iv) Restored Length: 37 M

Satisfactory

Aug  
20/07/22  
NE

He  
20/07/22  
mr

Vijay  
20/7/22  
Executive Engineer  
RWD, (W) Div...P. K. Pandey...

Name of Work:- Estimate for Repair of Road breaches (Damaged by Flood) for Motorability in Lakhaura-Adapur  
R.E.O. Road. To Bheriyahi For year 2021.

ad - FDR Length-2 KM

Item No.	Name of Item	unit	No	Length	Width	Height	Qty.	Rate	Amount
	Labour for laying dry graded Jhama Khon or stone filter under Brick Pitching or Boulder Pitching in slope or apron including light ramming etc. all complete as per approved design, specification and direction of E/L.	cum		As Per Appendix I			55.533 42.033	2060.40 1911.02	114420.00 86605.00 80325.00
TOTAL (in Rs.)									114420.00

Say Rs 114420.00 86605.00  
80325.00

*Chandra*  
Junior Engineer,  
Rural Works Department,  
Works Section, Adapur

*18/11/21*  
Assistant Engineer,  
Rural Works Department,  
Works Sub Division, Adapur

*18/11/21*  
Executive Engineer,  
Rural Works Department,  
Works Division, Raxaul

Post Facto T.A./T.S. is accorded for Rs. 80,300.00

.....crore...../.....lacs.....Eight.....thousand  
Three hundred ..... only.

.....crore.....

.....hundred.....

*18/03/2022*  
S.E. (R.W.D.)  
works Circle  
Motihari  
S.E. (R.W.D.)  
works Circle  
Motihari