Inspection Report for Flood Damage Work

Date: 20/4/22	
1. Name of PIUs - Executive Engine	er, R.W.D., Works, Division, Samantipus
2. Name of Block -	
3. Name of Road/Bridge	Nakta, Warishagar to Ballipur
A. for Road	7
1. Damage Location/Chainage	
2. Damage Length	0.800 KM
3. Nature of Damage	FT '
4. Details of Restoration Works :	
i. Material being used in Restoral	tion works: Bride Rate, Sand
ii. Equipments/Tools being used i	n Restoration Works: JCB & Toseter
iii. rrocedure taken up in Restorati	on works:
iv. Restored Length:	. 0 • 3 € 0 KM
B. for Bridge	
1. Damage Location/Chainage	
2. Damage Length	
3. Nature of Damage	
4. Details of Restoration Works :	
i. Material being used in Restoration	Off Works
ii. Equipments/Tools being used in	
iii. Procedure taken up in Restoratio	
iv. Restored Length:	Work have, found
	factory
Pole 1022 Mln	- Way
J.E. 15 104 10	12 ms. 4. 190 AT
A.E.	Executive Engineer, Signature R.W.D. Works Division, (Name of Inspector)
· × ×	(Name of Inspector)

(Name of Inspector)