

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 20.12.21 Name of PIU :-RWD (W) Div. ...*Sailhanga-2*

Name of Block :- BISFI

Name of Road :- BHAGAUTI TO NOORCHAK

For Road :-

1. Damage Location/ Chainage :- CH 1.2KM to CH 4.90KM

2. Damage Length :- 7m

3. Nature of Damage :- Breaches

4. Details of Restoration Works :- 15.16m³

i. Material being used in Restoration Works *Brick Bats*

ii. Equipment's/ Tools being used in Restoration Works : *Roller & Tractor*

iii. Procedure taken up in Restoration Works *Filling & Compaction*

iv. Restored Length : 7m

Remarks :- *Work found Satisfactory*

[Signature]
20.12.21
S.E.
Signature of JE/AE

[Signature]
20/12/21
Signature of E.E

Estimate for Restoration work of Road from Bhagauti to Noorchak for the year 2021-2022 in Bisfi Block

Length-6.263 KM

Sr NO.	Item of Work							
1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching in slope or							
Ch	Nos	Length	Width	Height	Quantity	Unit	Rate	Amount
1.2 Km	1	3.00	3.75 2.00	0.60	3.6 6.75			
4.90 Km	1	4.00	3.40	0.90	12.24	11.56		
					18.99	Cum	1939.93	36839.27

Add 12% GST

Add 1% L/Cess

Add Signorage Fee(18.99x1032x10%)

Total

=F

=R

=

=R:

4420.71

368.39

1959.77

43588.14

29409.33
3529.12
294.09
1564.51
34797.05

Say = 34797=00

[Signature]
20-11-21
JE
RWD

[Signature]
20/11/21
AE
RWD

[Signature]
20/11/21
EE
RWD

Bisfi

Bisfi

Benipatti

checked & verified for say = 15.16 M³

[Signature]
20.12.21
JE

[Signature]
20/12/21
AE

[Signature]
20/12/21

पत्रांक 492 दिनांक 28/03/22 कार्यपालक अभियंता दरभंगा-2 के ऑफिस के आधार पर

Technically sanctioned for Rs 34,797=00 (Thirty four thousand seven hundred ninety seven only)

Superintending Engineer
RWD Work Circle, Darbhanga

[Signature]
11/05/22