Inspection Report of Flood Damage work

Name of PIUs:- RWD Works Division, BIRAUL Name of Block/Road:- Gaurabauram/ Temporany Restoration of Gagniya gachi La Bishan peu. For Road A. 1. Damage Location Chainage: 170:04 2. Damage Length 3. Nature of Damage Pec Damage, Flank Damage 4. Details of Restoration Works Material being used in Restoration works:- Brick bat ii. Equipment's /Tools being used in Restoration works:iii. Procedure taken up in Restoration works: Brick bats filling: iv. Restored Length:-10.80 M For Bridge 1. Damage Location Chainage:-2. Damage Length 3. Nature of Damage 4. Details of Restoration Works Material being used in Restoration works:-Equipment's /Tools being used in Restoration works:iii. Procedure taken up in Restoration works:-• iv. Restored Length:work is satisfactory Signature of JE/AE/EE (Name of Inspection)

ABSTRACT OF COST

Road Name -

GAGHNIA GACHI TO BISHANPUR

Block Name -

Gaurabauram

Division -

Biraul

Cost of	brick	bat	including
---------	-------	-----	-----------

COSt Of Direct Da	it in loldding	
labour of materi	al -	

Add 12% of GST -
Add 1% of LC -
Add SF for bricks (10.72x1063x10%)

_			_	_	
2	1	4	9	3	

21493 2579

215

1140-1106

GAURABAURAM

Gaurabauram

Post facto The accorded for 1825,427/2 (Refeel)

Twenty fine thomased four hand and fixed,

ninty-three Joly in reference to letter no. 2187 dtd

13.12.2021 of EE, Red, MD Berbatti.

Superintending Engineer RWD, Works Circle, Darbhanga

GAGHNIA GACHI TO BISHANPUR

Supplying of bricks bat including labour for laying dry graded brick bat including the cost of labour material all complete job.

CHAINAGE	LENGTH	Breadth	HEIGHT	QTY
170	3.5	1.8	0.9	5.67
1,0	7.3	1+0.61+0.70/3	0.9 /	5.05
	6		TOTAL	10.72
	10-80 Mm		@ 2004.96	21493

	25427
Add SF for bricks (10.72x1063x10%)	-1140 1106
ADD 1% LABOUR CESS	215
ADD FOR GST 12%	2579
TOTAL AMOUNT	21493 —

JE Gaurabauram

Hat 2021

- 2021

- 2021

- 2021