

Inspection Report for Flood Damaged Work in the year 2021-22

Date of Inspection :- 20.12.21 Name of PIU :- RWD (W) Div. *Danbhangra-2*

Name of Block :- *BEHAPATTA*

Name of Road :- *TO7 TO BEHTA*

For Road :-

1. Damage Location/ Chainage :- *CH 1.300 KM*

2. Damage Length :- *30.50 m*

3. Nature of Damage :- *Breaches & Potholes*

4. Details of Restoration Works :- *26.43 m³*

i. Material being used in Restoration Works *Brick Bats*

ii. Equipment's/ Tools being used in Restoration Works *Roller & Tractor*

iii. Procedure taken up in Restoration Works *Filling & Compaction*

iv. Restored Length : *30.50 m*

Remarks :- *Work found Satisfactory*

20/12/21

Signature of E.E

20.12.21
Signature of JE/AE

Name of Road: T07 to Behta

Block : BENIPATTI

District: MADHUBANI

Length : 2.603 KM

Sr No.	Item	Item of Work	Nos	Length (M)	Width (M)	Depth (M)	Quantity	Unit	Rate	Amount
1	1.1	Labour for lying dry graded jhama khoa or Stone filter under Brick pitching or Boulder Pitching in slope or apron including light ramming etc. all complete as per approved design, specification and direction of E/I								
		CH 1.900 Km	1	20.00	1.10	0.50	11.000			
			1	9.00	1.20	0.60	64.800			
			1	1.50	2.80	0.60	2.520			
						Total	78.320	Cum	1939.93	151935.32

Add GST 12% Rs= 18232.24

Add Labour Cess 1% Rs= 1519.35

Add Signorage Fee (78.32x1032x10%) Rs= 8082.62

Total Rs= 179769.53

[Signature]
20/11/21

JE
RWD BENIPATTI

[Signature]
20/11/21

AE
RWD BENIPATTI

[Signature]
20/11/21

EE
RWD BENIPATTI

check & verified for qty = 26.43 M³

[Signature]
20/12/21
S.E

[Signature]
20/12/2021
A.E.

[Signature]
20/12/21

पत्रांक 492 दिनांक 28/03/22 कार्यपालक अभियंता दरभंगा-2 के जॉच के आधार पर

Technically sanctioned for Rs 60665=00 (Rupees sixty thousand six hundred sixty five only)

Superintending Engineer
RWD Work Circle, Darbhanga

Abhinav
11/05/22